

CORNER HISTORY:

| |
|------------------------------------|
| CORNER FILE CODE: T6S-R9W-E- 15 |
|------------------------------------|

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 24, 1805 "Post" (@.39.75 chains of 79.50 chains).

COUNTY SURVEYOR'S BOOKS: Book 1 P. 96: John C. Frory WCS Mar. 30, 1858 "One tree standing". Book 1 P. 243: O.B.Pasco WCS Dec.

18-20, 1865 (Mon. not identified).

OTHER SURVEYS AND PLATS: "Corner Code System" card shows an undated reference, monument not identified. "Corner Record" cord shows a 1988 reference to a 1" iron pipe 2" deep (by INDOT survey party).

VERIFICATION OF CORNER POSITION: September, 2002: The 1" O.D. iron pipe was found in place, reasonably consistent with the 1988 INDOT reference ties.

June, 2005: The 1" O.D. iron pipe was found in place; reasonably consistent with 1988 INDOT reference ties. Measurements were made to the reference points using tape measure. Fnd. Nail/Bottle Cap in SE Side of Wood Fence Post was not found; Wood fence post was destroyed or removed.

Perry E. Jones 9/23/02

Brian Schnur and Dan Grady 6/16/05