

CORNER HISTORY:

CORNER FILE CODE:  
T6S-R9W-R-07

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 19, 1805 "Post".

COUNTY SURVEYOR'S BOOKS: Book 1 P. 57: W.B. Wright WCS November, 1855 (Not identified, Stone presumed) Book 1 P.

238: O.B.Posco WCS Nov. 25, 1865 "Stoke Set"

OTHER SURVEYS AND PLATS: Plot of survey by John W. Curry dated 12/30/87 (unrecorded, copy provided by Donald Adler) shows PK nail found.

Location Control Route Survey for SR 66 (Doc. 1997R-007361) tied in a 1" pin in monument box. The section ties for this project were done in 1990. The monument box is thought to have been constructed under INDOT Proj. 1-164-1 (1986). Road plans for that

project identified the P.I. as being the 1/4-section corner.

An Exempt Division by Donny K. Leek dated October 22, 1998 showed the iron pin in monument box.

The monument box is known to have been destroyed during lane additions along SR 66 around 1999. A new point) was set 18.18' north of 1" iron pin (alignment the monument box's location.

VERIFICATION OF CORNER POSITION: September, 2002; the former location of the old monument box was re-established from ties to survey control points from the 1990 S.R. 66 survey. March, 2003; falling within the present travel lanes of S.R. 66, the corner itself was not reset; two witness points were set in addition to the new 1" iron pin in the intersection. By occupying the 1" iron pin a 90' angle can be turned from either of the other witnesses to recreate the calculated point at the distance shown.

Perry E. Jones 3/13/03