

CORNER HISTORY:

CORNER FILE CODE:  
T6S-R9W-T-21

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 18, 1805 "Post".

COUNTY SURVEYOR'S BOOKS: Book 1 P. 29: Isaac Adams WCS August 1, 1854 "Stone". Book 1 P. 218:

O.B.Pasco WCS March 2, 1865 "Wood Post by Former Surveyor".

OTHER SURVEYS AND PLATS: "Corner Code System" card includes an undated reference to a 1/2" IP.

Location Control Route Surveys for SR 66 (Docs. 1997R-007360) (section corner ties performed in 1991) show a 1/2" rebar, reasonably consistent with county reference ties and deed dimensions to nearby property corner monuments.

VERIFICATION OF CORNER POSITION: The 1/2" rebar was found in place, and checked against the county reference ties and SR 66 survey.

June, 2005: The 1/2" rebar was found in place, and measured accurate, using tape, to reference points less than 200'. The PK Nail in PwP #77-303 was not found, the pole had not been replaced.

Perry E. Jones 9/3/02

Brian Schnur and Dan Grady 6/17/05