

CORNER HISTORY:

CORNER FILE CODE: T6S-R9W-R-15

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 20, 1805 "Post".

COUNTY SURVEYOR'S BOOKS: Book 1 P. 56: W.B. Wright WCS Nov. 1, 1855 "Stone"

OTHER SURVEYS AND PLATS: "Corner Record" card shows references to PK nail as taken from the 1979 plat of Bell Oaks Subdivision.

A 1/2" rebar was tied in and referenced on the Bell Road Route Survey (Bernardin-Lochmueller & Assoc. 1989, unrecorded). Reference ties matched those to the PK shown on the County Surveyor's "Corner Record" card.

Location Control Route Survey for SR 66 (Doc. 1997R-007361) (section corner ties for this survey were performed in 1990); the 1/2" rebar was tied in and referenced.

A plot of survey by James Q. Morley (Doc. 1996R-004748) shows a 1/2" iron rod found.

VERIFICATION OF CORNER POSITION: June, 2002: Dimensions shown on the 1996 Morley survey were compared with the SR 66 Location Control Route Survey and found to be reasonably consistent. Additional ties to the 1/2" rebar shown were obtained.

Construction work currently in progress along SR 66 will include removal of the existing pavement and monuments; construction plans call for the placement of a section corner monument.

P
e
r
r
y

E
-

J
o
n
e
s

Z
Z
g
Z
O
3